

One of our customers was experiencing repeated and consistent failures of the reheat structural frame and walking beams. They had welding crews repairing cracks weekly. DynaIndustrial performed detailed finite element analysis (FEA) of the structure and designed upgrades that were relatively easy to install, eliminated the weak points and created a reliable structure. Five years later, the customer has only performed occasional inspections; no further repair work has been required.

