

Utilizing the expertise of our team we worked in collaboration with the customer to resolve their existing reheat charge and extraction equipment design flaws.

We redesigned the slab squaring system to prevent the foundation and equipment from damage.

We also created access points for ease of roll maintenance.

